



REVISIONS				
REV.	ECN NO.	DESCRIPTION	BY	DATE
A	42389	RELEASE FOR PRODUCTION	JRL	6/16/2023



SCALE 0.250




FASTENER HEAD TO BE FLUSH OR RECESSED FROM TOP SURFACE WHEN INSTALLED

2-1/2 [63.5] MAXIMUM DISTANCE TO RUB RAIL

Ø13/32 [9.9] ALL MOUNTING HOLES

MUST USE COUNTERSUNK HEAD SCREWS TO MOUNT PUCK

SECTION A-A





- NOTES:
- RECOMMENDED DRILL SIZE 13/32
 - MOUNTING FASTENERS TO BE MINNKOTA SUPPLIED 3/8-16 WITH COUNTERSUNK HEADS


CAUTION: ALWAYS WEAR SAFETY GLASSES AND GLOVES. DISCONNECT ALL POWER BEFORE BEGINNING ANY WORK OR MAINTENANCE. JOHNSON OUTDOORS INC. IS NOT RESPONSIBLE FOR ANY DAMAGE DUE TO IMPROPER RIGGING OR INSTALLATION. IF YOU DO NOT HAVE THE SKILLS, EXPERIENCE AND TOOLS TO PERFORM THE FOLLOWING MAINTENANCE AND REPAIRS, WE RECOMMEND YOU SEEK THE HELP OF AN AUTHORIZED SERVICE CENTER. OR CONTACT OUR TECHNICAL SERVICE DEPARTMENT BY DIALING 800-227-6433.

CUSTOMER DRAWING			
JOHNSON OUTDOORS MARINE ELECTRONICS, INC.			
DRAWING NAME:	1854.055/1854.056	U/M:	IN.
DRAWING NO:	CD0001	REV:	A


REVISIONS				
REV.	ECN NO.	DESCRIPTION	BY	DATE



MOTOR SECURED WITH DRAWBAR



DRAWBAR REMOVAL CLEARANCE



CAUTION: ALWAYS WEAR SAFETY GLASSES AND GLOVES. DISCONNECT ALL POWER BEFORE BEGINNING ANY WORK OR MAINTENANCE. JOHNSON OUTDOORS INC. IS NOT RESPONSIBLE FOR ANY DAMAGE DUE TO IMPROPER RIGGING OR INSTALLATION. IF YOU DO NOT HAVE THE SKILLS, EXPERIENCE AND TOOLS TO PERFORM THE FOLLOWING MAINTENANCE AND REPAIRS, WE RECOMMEND YOU SEEK THE HELP OF AN AUTHORIZED SERVICE CENTER. OR CONTACT OUR TECHNICAL SERVICE DEPARTMENT BY DIALING 800-227-6433.

CUSTOMER DRAWING			
JOHNSON OUTDOORS MARINE ELECTRONICS, INC.			
DRAWING NAME:	1854055/1854056	U/M:	REV: A
DRAWING NO:	CD0001	IN.	